



no	name	qua.	no	name	qua.
1	computer	1	42	left collar housing	2
2	foam	2	43	nut	1
3	handle pulse (ø 25)	2	44lr	washer	1
4	end cap (ø 25)	2	45	spring knob	1
5	handlebar	1	46	belt	1
6	screws st4.2x19	2	47	crank wheel	1
7	handlebar cover	1	48	rear stabilizer	1
8	bolt m8x30	2	49	enc cap ø60	2
9	spring washer	2	50	plastic wheel	1
10	sensor wire	2	51	bolt m10x1.0	1
11	bolt m5x15	1	52	tension spring	1
12	moter	1	53	belt bracket	1
13	suppost tube	1	54	nut m10x1.0	2
14	middle wire	1	55	bolt	2
15	bolt m4x12	4	56	nut m10x1.0	2
16	Screw M5*10	4	57	flywheel	1
17	arc washer d8xø20x1.5xr25	8	58	washer d8xø20x2	1
18	bolt	4	59	bearing	2
19	seat	1	60	axle	1
20	seat bracket	1	61	hex nut m10*1*2.5	1
21	washer d8x ø 16x1.5	3	62	plastic lattice	1
22	nylon nut	5	63	magnet	4
23	end cap j40x20	2	64	magnetic board	1
24	seat post	1	65	axle	1
25	knob m8x15	1	66	snap spring d12	2
26	sensor wire	1	67	bolt m6*16	2
27	tension wire	1	68	spring washer d6	2
28	d plastic insert	1	69	washer d6*ø16x1.5	2
29	main frame	1	70	tensin spring	1
30	rear end cap ø60	2	71	bolt m6*36	1
31	front stabilizer	1	72	nut m6	2
32	carriage bolt m8x72	4	73	Sensor wire	1
33	domed nut m8	4	74	Power supply wiring	1
34lr	pedal	2	75	Nut M12*1	1
35	crank cover	2	76	Power adapter	1
36	chain cover	2	77	Wahher d4*ø12x1.0	4
37	screws st4.2x19	13			
38	nut	1			
39	washer	1			
40	washer ii	1			
41	collar ball	2			